

Mine Name: Skull Valley Diatom Earth

Operator Name: Holcim (US) Inc.


State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R STYLER
Executive Director

JOHN R BAZA
Division Director

Inspection Report Minerals Regulatory Program

Date: March 15, 2009



Permit Number: M/045/0060

Inspection Date: 10-01-2008

Inspector(s): L Heppler			
Other Participants: none			
Elements of Inspection	Evaluated	Comment	Enforcement
1 Permits, Revisions, Transfer, Bonds	\boxtimes	\boxtimes	
2 Public Safety (shafts, adits, trash, signs, highwalls)	\boxtimes		
3. Protection of Drainages / Erosion Control			
4. Deleterious Material			\vdash
5 Roads (maintenance, surfacing, dust control, safety)			
6. Reclamation			H
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,		님	H
8 Soils	X	\vdash	H
9. Revegetation	X		

Bond Renewal Date: 08-30-2008 Bond Amount: \$170,900 Permit fee is up to date

Purpose of Inspection: Routine annual Inspection

Inspection Summary: Site has been regraded, no trash at site, entrance of road has been bermed. No revegetation has been done, weeds dominate the site.

Photos were taken to document site conditions.

Conclusions and Recommendations: Operator should eradicate weeds, and use a temporary cover crop. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature LAH:vs

LAHIVS

cc: Lance Stephens

BLM - Larry Chandung arblem nov Stephen Allen@blm.gov

O:\M045-Tooele\M0450060-SkullValleyDiatoms\inspections\insp_10012008 doc

